



SPECIFIC FIT HEADERS

YEARS	ENGINES	UNCOATED	METALLIC CERAMIC COATED	EMISSION CODES	FOOTNOTES	AUTO			STD		TUBE SIZE	COLLECTOR SIZE	PORT SHAPE			
						A/C	P/B	P/S	COL	FLR				COL	FLR	
DODGE / PLYMOUTH																
ALL B & E (A & F) BODIES																
	67-82	273-360	H8206	H8206-1	203		Y	Y	Y	Y	Y	N	Y	15/8"	3"	SAP
NEW	67-74	383-440	H8207	H8207-1	203		Y	Y	Y	Y	Y	Y	Y	17/8"	3"	SAP
CHALLENGER /BARRACUDA																
NEW	60-74	383-440	H8207	H8207-1	203		Y	Y	Y	Y	Y	Y	Y	17/8"	3"	SAP
CHRYSLER CORDOBA																
NEW	1975	400	H8207	H8207-1	203		Y	Y	Y	N	Y	N	N	17/8"	3"	SAP
FORD / MERCURY																
MUSTANG / COUGAR																
	64-70	260-302W	H8426	H8426-1	26, 83, 84, 97, 102		Y	Y	Y	Y	Y	N	Y	1 1/2"-1 3/4"	2 1/2"	OVL
NEW	64-73	260-302W	H8433	H8433-1	5, 18, 62, 64, 196, 197		Y	Y	Y	Y	Y	N	Y	1 5/8"	3"	OVL
	64-73	260-302W	H8403	H8403-1	91, 98, 99		Y	Y	Y	N	Y	N	Y	15/8"	3"	SAP
	67-70	351C	H8407	H8407-1	88, 97		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	67-70	351C	H8408	H8408-1	88, 97		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	67-70	351C	H8409	H8409-1	88, 97		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
	67-70	351C	H8411	H8411-1	88, 97		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
	67-73	351W	H8403	H8403-1	91, 97, 98, 99		Y	Y	Y	N	Y	N	N	15/8"	3"	SAP
	71-73	351C	H8412	H8412-1	88, 97		Y	Y	Y	N	Y	N	Y	13/4"	3"	SAP
	71-73	351C	H8413	H8413-1	88, 97		Y	Y	Y	N	Y	N	Y	13/4"	3"	SAP
FAIRLANE, TORINO/ CYCLONE, MONTEGO																
NEW	66-73	260-302W	H8433	H8433-1	5, 18, 62, 196, 197		Y	Y	Y	Y	Y	N	Y	1 5/8"	3"	OVL
	66-73	260-302W	H8403	H8403-1	97, 98, 99		Y	Y	Y	Y	Y	N	Y	15/8"	3"	SAP
	67-73	351W	H8403	H8403-1	97, 98, 99		Y	Y	Y	Y	Y	N	Y	15/8"	3"	SAP
	70-71	351C	H8407	H8407-1	88, 97		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	70-71	351C	H8408	H8408-1	88, 97		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	70-71	351C	H8409	H8409-1	88, 97		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
	70-71	351C	H8411	H8411-1	88, 97		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
FALCON																
NEW	66-70	260-302W	H8433	H8433-1	5, 18, 62, 64, 196, 197		Y	Y	Y	Y	Y	N	Y	1 5/8"	3"	OVL
	66-73	260-302W	H8403	H8403-1	97, 98		Y	Y	Y	Y	Y	N	Y	15/8"	3"	SAP
COMET																
	66-69	260-302W	H8403	H8403-1	97, 98		Y	Y	Y	N	Y	N	Y	15/8"	3"	SAP
RANCHERO																
	66-73	260-302W	H8403	H8403-1	97, 98, 99		Y	Y	Y	Y	Y	N	Y	15/8"	3"	SAP
	70-71	351C	H8407	H8407-1	97, 88		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	70-71	351C	H8408	H8408-1	97, 89		Y	Y	Y	N	Y	N	N	13/4"	3"	SAP
	70-71	351C	H8409	H8409-1	97, 88		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
	70-71	351C	H8411	H8411-1	97, 89		Y	Y	Y	N	N	N	Y	13/4"	3"	SAP
PICKUP																
	53-56	223	H8425		58, 59		Y	Y	Y	Y	Y	N	Y	1 1/2"	2"	REC
	53-56	272-312Y	H8440		4		Y	Y	Y	Y	Y	N	Y	1 1/2"	3"	SAP
	54-64	272-292Y	H8422		110		Y	Y	Y	Y	Y	N	Y	1 1/2"	3"	SAP
2WD F150																
	65-74	260-302W	H8405	H8405-1	90, 100		Y	Y	Y	Y	Y	N	N	15/8"	2 1/2"	SAP
	65-76	352-390	H8406	H8406-1			Y	Y	Y	Y	Y	Y	Y	13/4"	3"	SAP
2WD F250																
	65-74	260-302W	H8405	H8405-1	90, 100		Y	Y	Y	Y	Y	N	N	15/8"	2 1/2"	SAP
	65-76	352-390	H8406	H8406-1			Y	Y	Y	Y	Y	Y	Y	13/4"	3"	SAP
4WD F250, F350																
	65-74	260-302W	H8405	H8405-1	90, 100		Y	Y	Y	Y	Y	N	N	15/8"	2 1/2"	SAP



SPECIFIC FIT HEADERS

YEARS	ENGINES	UNCOATED	METALLIC CERAMIC COATED	EMISSION CODES	FOOTNOTES	AUTO			STD		TUBE SIZE	COLLECTOR SIZE	PORT SHAPE			
						A/C	P/B	P/S	COL	FLR				COL	FLR	
OLDSMOBILE																
CUTLASS / 442																
65-75	400-455	H8101	H8101-1	⬡	163	Y	Y	Y	Y	Y	N	Y	1 3/4"	3"	SAP	NEW
68-77	350-403	H8100	H8100-1	⬡	163	Y	Y	Y	Y	N	N	Y	1 5/8"	2 1/2"	SAP	
DELTA 88																
71-75	400-455	H8101	H8101-1	⬡		Y	Y	Y	Y	Y	N	N	1 3/4"	3"	SAP	NEW
VISTA CRUISER WAGON																
71-74	400-455	H8101	H8101-1	⬡		Y	Y	Y	Y	Y	N	N	1 3/4"	3"	SAP	NEW
PONTIAC																
FIREBIRD, TRANS AM																
67-69	350-455	H8302	H8302-1	⬡	104	Y	Y	Y	N	Y	N	Y	1 5/8"	3"	SAP	NEW
70-79	350-455	H8301	H8301-1	⬡	104	Y	Y	Y	N	Y	N	Y	1 5/8"	3"	SAP	NEW
77-78	350-403 OLDS	H8100	H8100-1	⬡		Y	Y	Y	N	Y	N	Y	1 5/8"	2 1/2"	SAP	
GTO, LE MANS, GRAND AM																
64-75	326-455	H8301	H8301-1	⬡	104	Y	Y	Y	N	Y	N	Y	1 5/8"	3"	SAP	

CLASSIC IMPORT HEADERS

YEARS	ENGINES	UNCOATED	METALLIC CERAMIC COATED	EMISSION CODES	FOOTNOTES	AUTO			STD		TUBE SIZE	COLLECTOR SIZE	PORT SHAPE			
						A/C	P/B	P/S	COL	FLR				COL	FLR	
JAGUAR																
XKE E-TYPE SERIES 1&2																
61-71	3.8-4.2L	H4830	H4830-1	⬡	103	Y	Y	Y	Y	Y	N	Y	1 5/8"	2 1/2"	REC	
MG																
MGB, MGB-GT																
PRE 75	1.8L	H4800	H4800-1	⬡		Y	Y	Y	N	N	N	Y	1 3/8"	2"	RD	
MIDGET																
75-80	1.5L	H4803		⬡		Y	Y	Y	N	N	N	Y	1 1/4"	2"	OVL	
VOLVO																
544, 120, 140, P1800, P1800S, P1800ES																
62-69	B18, B20	H4850	H4850-1	⬡	32	Y	Y	Y	N	N	N	Y	1 1/2"	2"	REC	
62-69	B18, B20	H4851	H4851-1	⬡	75	Y	Y	Y	N	N	N	Y	1 1/2"	2"	REC	

Footnotes

<p>4 Fenderwell exit</p> <p>5 Shorty design for maximum ground clearance</p> <p>18 Header installation requires the use of the 1965-66 Non Hi-Po V8 clutch equalizer bar</p> <p>26 67-70 models require additional driver's side header clearance around the steering box</p> <p>32 Fits only when a 62-67 type intake manifold is used</p> <p>58 Header uses dual collector design for increased torque</p> <p>59 Fits the flathead six engine but does not provide for heat exchange to the stock cast intake manifold</p> <p>62 Must use 66 1/2 or later frame brackets (approx. 1" higher than 65 and early 66 style)</p> <p>64 Fits with manual transmissions using 85-95 bellhousings with cable clutch kits</p>	<p>75 Fuel injected engines only</p> <p>83 Fits with manual transmissions using 10" or 10.5" clutch only. 1968-up bellhousings require driver's side header clearance</p> <p>84 Non-HiPo cars with manual transmission may need header clearance for clutch linkage</p> <p>88 Fits two barrel heads</p> <p>89 Fits four barrel heads (Boss 351)</p> <p>90 Does not fit with C-6 transmission</p> <p>91 Will not fit Dart/Windsor heads</p> <p>97 Installation requires power steering bracket PN H7609.</p> <p>98 Fits with C-6 transmission.</p> <p>99 Does not fit 1971-73 Mustang/Cougar with manual transmission.</p>	<p>100 Will not fit models with air injection cylinder heads</p> <p>102 Replica of early Shelby Tri-Y header.</p> <p>103 See page 21 for Jaguar exhaust system listings.</p> <p>104 Some factory heads do not have end bolt holes and should be drilled and tapped to assure proper sealing.</p> <p>110 Fits 1953 models with transplanted Y block engines when 1954-64 Y block motor mounts are used.</p> <p>163 Does not fit Cutlass Supreme</p> <p>196 Lakewood bell housings require clearancing for header tubes</p> <p>197 Use recommended C5ZZ16A052E "export brace" if shock mount center to center dimension is less than 33 3/4"</p> <p>203 Will not fit models equipped with air injection pump without modification</p>
--	---	---